

**STRIETER-LITE Wild Animal Highway Warning Reflector System**

**Reflectorized Section**

Location:	Worthington Avenue, 0.25 miles west of Reisterstown		
Length of Reflectorized Section:	1.5 miles		
Reflectors Installed:	26 Sep 1996		
Reflector Installation Design:	Directed across highway and staggered		
Terrain:	Level and Curves		
Deer-Vehicle After Dark Crash History Prior to Installation:	1/95 to 12/95: 7	1/96 to 9/96: 9	
Number of After Dark Crashes After Installation:	1997: 0	1998: 0	1999: 0
<b>Reduction: 100%</b>			
Period of Study:	Sep 96 to Dec 99		
Estimated Reflector Maintenance Costs: Oct 96 – Dec 98: Replaced 20 reflectors, 25 posts, 8 man-hours = \$558. OR \$280 / yr / mi average			

Reflector Purchases	
Initial Purchase	Subsequent Purchases
9/96 - received 210 from MD DOT	2/97 - 20

Reisterstown, MD  
Worthington Ave. between  
Butler Road & Sagamore  
Forest Lane.  
Photo: 9/26/97

