

STRIETER-LITE Wild Animal Highway Warning Reflector System

Reflectorized Section

Location:	State Route 3 5.8 miles north of Mexico. RP 3-3401-3210 to 3-3401-3229
Length of Reflectorized Section:	1.9 mi
Reflectors Installed:	1996
Reflector Installation Design:	Directed across highway and staggered
Terrain:	Slightly Hilly, Level and Curves
Deer-Vehicle After Dark Crash History Prior to Installation:	Unknown -
Number of After Dark Crashes After Installation:	Reduced
Period of Study	1996 - Mar 99

Remarks: Actual number of deer/vehicle collisions are not compiled at this office. However, information received from crews that pick-up the animals have indicated a reduction in the number of animals hit on this section of highway.

Prepared/Approved by: James Tompkins

Title: Assistant Resident Engineer